



# GARDEN WOOD LATEST IMAGES



# FRONT ELEVATION LATEST IMAGES



# BLOCK-A Images

Work completed external plastering and external texture, External plumbing shafts work on progress & Above terrace activity OHT concrete work completed.



# BLOCK-A 1<sup>st</sup> Floor Images

Internal putty first coat completed in all units, Toilet sunken water proofing & internal water line and waste water line completed in all units.



# BLOCK-B Images

External plastering work on progress & Above terrace activity OHT cover slab work progress..



# BLOCK-B 1<sup>st</sup> Floor Images

Door frame work completed in all units, Kitchen counter work on progress.



# BLOCK-C Images

Concrete done by water tank , Tiling work started in 2&3<sup>rd</sup> floor.



# BLOCK-C 1<sup>st</sup> Floor Images

UPVC window fixing completed, Kitchen counter work on progress.





# BLOCK-D Images

Concrete done by water tank & Store room, 2 Floor shuttering work on progress.



# BLOCK-D 1<sup>st</sup> Floor Images

Internal plastering work on progress.



# Sales Office Area

